

# **ER. MANISH KUMAR SINGH**

**B.E ( CIVIL-BPUT ) MBA (DELHI UNIVERSITY )**

**B/1, SURYA ENCLAVE, BALIAPANDA, PURI-752001**

---


Ref No. 2A/2024

Date.: 01/03/2024

## **BUILDING SAFETY CERTIFICATE**

This is to certify that, at the request of Principal, DAV School, Puri I have inspected the School Building of DAV Public School, situated at Water Works Road, Puri on dated 28<sup>th</sup> February 2024, in the capacity of Chartered Engineer ( Civil ) and found the present condition of the structure is safe in all respect.

It is my suggestion to maintain & paint the building regularly, both in & out side , for longevity of the building and to save from salty climate.

  
**Er, Manish Kumar Singh**  
**B.E (Civil MBA**  
**B/1. Surya Enclave**  
**Baliapanda, Puri, Odisha**  
**ER. MANISH KUMAR SINGH**